



Machine	Explode	Code	Description	Stocked Line
P108	1	n/a	Griddle Plate	n/a
P108	2	N496	Heating Element	✓
P108	3	N125	300c Thermostat	✓
P108	4	n/a	Insulation Clamp	n/a
P108	5	N126	120c Thermal Cut Out	✓
P108	6	N150	Plug & Lead	✓
P108	7	n/a	Feet	✓
P108	8	N129	Dial	✓
P108	9	N486	Indicator Light	✓
P108	10	N498	Drip Tray	✓
P108	11	n/a	Element Clamp	n/a